

Project Name
Dubbo Hospital
Stage 4

Client Name
NSW Health
Infrastructure

Contractor
Hansen Yuncken

Aspect	KPI's	Status – August 2018
Site Accommodation	<ul style="list-style-type: none"> Appropriate location and operation of all facilities. Site reinstated upon completion of project. 	Compliant.
Air Quality (including Dust)	<ul style="list-style-type: none"> Visual observance of dusts levels; vehicle and plant emissions No dust complaints. 	Dust monitored and managed on site.
Noise	<ul style="list-style-type: none"> No complaints concerning noise nuisance. No fines received. 	No noise complaints received. No fines received.
Vibration	<ul style="list-style-type: none"> No disturbances/incidents or complaints. 	No complaints
Water Quality – Erosion and Sediment Control	<ul style="list-style-type: none"> No incidents of inadvertent waste of water. No run-off of sediment No pollution or contamination of waterways. 	None to date.
Spill Management and Response	<ul style="list-style-type: none"> No spillages. Spill kits readily accessible. 	No spillages to date.
Identification and Protection of Existing Utility Services	<ul style="list-style-type: none"> No unplanned interruptions to any utility service. 	None to date.
Waste Management	<ul style="list-style-type: none"> No incidents arising from the disposal of end waste. 	The EPA attended site to follow up on a complaint of 'Illegal Dumping of Asbestos'. The EPA confirmed that they were satisfied that no illegal dumping activities had taken place from this site. EPA tipping records on the EPA WasteLocate website were up to date.
Vehicular and Pedestrian Traffic Management	<ul style="list-style-type: none"> Reports or complaints of interruption or interference with pedestrian or vehicular traffic movement around the site. 	None to date.
Hazardous Substances and Dangerous Goods	<ul style="list-style-type: none"> No spillages, incidents or complaints 	None to date.
Vermin and Pest Control	<ul style="list-style-type: none"> No infestations. 	None to date.

Commuting Mass Transport	<ul style="list-style-type: none">• Site personnel are using alternative means of transport.	Site personnel are encouraged to use alternate means of transport.
Site Amenities	<ul style="list-style-type: none">• No odour or vermin present	None present.
